

Facility Report

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Gym						
Path of Travel						
<i>Gym East Side Sidewalk</i>						
Record Number: 1406						
There are slopes greater than 5% on the primary path of travel to the Gymnasium. There are cross slopes greater than 2% on the primary path of travel.	Resurface the path of travel to provide a level surface that does not exceed a slope greater than 5%. Cross slopes shall not exceed 2%.	\$1,440.00				
<i>Gym Main Entrance</i>						
Record Number: 1398						
The mat carpet runner does not adhere to the underlying floor surface and creates a hazardous path of travel.	Securely fasten the mats carpet runners or replace with a mat carpet runner that grips to the underlying floor surface to provide a firm, stable, continuous and relatively smooth path of travel surface (see CBC 1124B.3 and ADAAG 4.5.3). Mats or carpet runners along the primary path of travel shall provide beveled edges on all sides to prevent roll over.	\$659.00				
Gym						
Ramps						
<i>Gym Exterior Ramp to the Bridge</i>						
Record Number: 1403						
The length of the ramp exceeds the maximum distance allowed for its slope (rise).	Provide an intermediate landing on the ramp complying with CBC 1133B.5.4.1 and ADAAG 4.8.4 with a rise for each run of the ramp not exceeding 30 inches in height (see also ADAAG 4.8.2).	\$4,920.00				
Record Number: 1404						
The ramp has no handrails.	Install handrails on each side of the ramp that provide a continuous and smooth gripping surface diameter between 1 1/4 inches to 1 7/8 inches, mounted at a height between 34 inches and 38 inches and shall be at a distance no less than 1 1/2 inches from the adjacent wall. The ends of the handrails shall extend 12 inches in a parallel height from the top and bottom of the ramp and return smoothly to the post or wall.	\$1,200.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Gym Stage Ramps						
Record Number: 1393 The width of each run of each ramp is less than 48 inches.	Widen each run of each ramp so that it has a minimum clear width of 48 inches (see CBC 1133B.5.2.2).	\$15,000.00				
Record Number: 1394 The slope of each run on each ramp is greater than 8.33%.	Modify each run of each ramp to provide a slope no greater than 8.33% with a cross slope not exceeding 2% (see CBC 1133B.5.3 and ADAAG 4.8.2).	\$4,920.00				
Record Number: 1395 The length of the intermediate switchback landing on each ramp is less than 72 inches.	Modify or replace the intermediate switchback landing on each ramp to provide at least 72 inches in length in the direction of the run of the ramp and at least 96 inches in width to incorporate the minimum width of each run of the ramp and the distance between the parallel runs (see CBC 1133B.5.4.6 and ADAAG 4.8.4).	\$1,872.00				
Record Number: 1396 The length of the top landing on each ramp is less than 60 inches.	Modify or replace the top landing on each ramp to provide a top landing that exceeds 60 inches in length and 60 inches in width with a level surface that does not exceed a slope greater than 2% and provide at least 42 inches distance between the latch side of the door and the side of the landing to accommodate the required side approach to the entrance door (see CBC 1133B.5.4.2 and ADAAG 4.8.4(2)).	\$1,872.00				
Record Number: 1397 The handrails on each ramp are mounted at a height greater than 38 inches.	Modify or replace the handrails on the ramp to provide a gripping surface height between 34 inches and 38 inches above the ramp surface (see CBC 1133B.5.5 and ADAAG 4.8.5).	\$3,918.00				
Gym						
Doors						
Gym Main Entrance Door						
Record Number: 1365 The door opening force for some of the exterior and interior doors is greater than 5 pounds of force.	Adjust the closers on all exterior and interior doors to a maximum door opening force of 5 pounds of force (see ADAAG 4.13.11 and CBC 1133B.2.5).	\$5.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
<i>Gym Main Entrance</i>						
Record Number: 1399						
The clear opening width of the double doors is less than 32 inches.	Widen both of the double door openings and install doors that provide at least 32 inches of clear width with each door open 90 degrees (see CBC 1133B.2.3.1 and ADAAG 4.13.5).	\$1,611.00				
<i>Gym Men's Locker Room</i>						
Record Number: 1358						
The interior passage door has push-bar/thumblatch hardware.	Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9).	\$834.00				
Record Number: 1359						
The clear opening width of the double doors is less than 32 inches.	Widen both of the double door openings and install doors that provide at least 32 inches of clear width with each door open 90 degrees (see CBC 1133B.2.3.1 and ADAAG 4.13.5).	\$1,611.00				
<i>Gym Men's Locker Room Door to the Pool</i>						
Record Number: 1364						
The clear opening width of the double doors is less than 32 inches.	Widen both of the double door openings and install doors that provide at least 32 inches of clear width with each door open 90 degrees (see CBC 1133B.2.3.1 and ADAAG 4.13.5).	\$1,611.00				
<i>Gym North Entrance</i>						
Record Number: 1390						
The exterior passage doors have push-bar/thumblatch hardware.	Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9).	\$834.00				
Record Number: 1391						
The height of the threshold at the entrance door is greater than 1/2 inch.	Install a threshold ramp with a slope not exceeding 8.33% to the threshold at the doorway. Another option is to provide a threshold treatment ramp to the entrance door.	\$2,500.00				
Record Number: 1392						
The bottom 10 inches of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition, due to the door stop.	Remove the door stop to provide a smooth, uninterrupted surface for the bottom 10 inches of the door.	\$0.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Gym Physicla Education Office						
Record Number: 1384						
The bottom 10 inches of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition, due to the door stop.	Remove the door stop to provide a smooth, uninterrupted surface for the bottom 10 inches of the door.	\$0.00				
Record Number: 1385						
The interior passage door has a round doorknob, which requires twisting of the wrist to operate.	Interior door hardware (doorknobs) should be changed to accessible lever-handled lockset hardware (see ADAAG 4.13.9).	\$204.00				
Gym Training Room 136						
Record Number: 1387						
The exterior passage door has push-bar/thumblatch hardware.	Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9).	\$834.00				
Gym Weight Training Room 135						
Record Number: 1388						
The exterior passage door has a round doorknob, which requires twisting of the wrist to operate.	Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9).	\$834.00				
Record Number: 1389						
The height of the threshold at the entrance door is greater than 1/2 inch.	Install a threshold ramp with a slope not exceeding 8.33% to the threshold at the doorway. Another option is to provide a threshold treatment ramp to the entrance door.	\$2,500.00				
Gym Women's Locker Room						
Record Number: 1334						
The interior passage door has push-bar/thumblatch hardware.	Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9).	\$834.00				
Record Number: 1335						
The clear opening width of the double doors is less than 32 inches.	Widen both of the double door openings and install doors that provide at least 32 inches of clear width with each door open 90 degrees (see CBC 1133B.2.3.1 and ADAAG 4.13.5).	\$1,611.00				
Gym Women's Locker Room Door to the Pool						
Record Number: 1339						
The clear opening width of the double doors is less than 32 inches.	Widen both of the double door openings and install doors that provide at least 32 inches of clear width with each door open 90 degrees (see CBC 1133B.2.3.1 and ADAAG 4.13.5).	\$1,611.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1340 The exterior passage door has push-bar/thumblatch hardware.	Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9).	\$834.00				
Record Number: 1341 The height of the threshold at the entrance door is greater than 1/2 inch.	Install a threshold ramp with a slope not exceeding 8.33% to the threshold at the doorway. Another option is to provide a threshold treatment ramp to the entrance door.	\$2,500.00				
Gym Women's Locker Room Restroom						
Record Number: 1336 The clear opening width of the double doors is less than 32 inches.	Widen both of the double door openings and install doors that provide at least 32 inches of clear width with each door open 90 degrees (see CBC 1133B.2.3.1 and ADAAG 4.13.5).	\$1,611.00				
Gym Restrooms						
Gym Men's Restroom						
Record Number: 1368 There is no signage indicating accessibility on the latch side of the entry door of the restroom. There is no Title 24 gender use signage on the entrance door.	The restroom is designated accessible and should be made accessible for the facility. Post signage centered 60 inches above the ground surface on the latch side of the entrance door identifying the restroom as accessible upon completion of the following items (see CBC 1115B., ADAAG 4.1.2(7) and ADAAG 4.1.6(3)(e). Signage shall include Braille and raised lettering, the gender or unisex use symbol and the ISA symbol. Post Title 24 gender use signage on the door @ 60" o.c. a.f.f.	\$58.00				
Record Number: 1369 There is less than 12 inches on the latch side of the entrance door to the restroom from the push side.	Consult a design professional to determine if it is technically feasible to provide at least 12 inches of latch side clearance at the entrance door to the restroom from the push side (see ADAAG 4.13.6 and Figure 25). Otherwise, an automatic door opening device may be required to provide an accessible entrance.	\$0.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1370 The urinal in the restroom does not provide a tapered, elongated rim. The height of the urinal rim is greater than 17 inches above the finished floor. The flush control valve on the urinal is greater than 44 inches above the finished floor.	Replace the urinal designated to be accessible in the restroom with a wall-mounted or stall-type tapered, elongated rim unit complying with ADAAG 4.18.2. The height of the rim surface of the urinal designated to be accessible shall not exceed 17 inches above the finished floor and the flush control valve shall not exceed a height of 44 inches above the finished floor.	\$951.00				
Record Number: 1371 There is insufficient clear floor space in the stall designated to be accessible in the restroom. The width of the stall is less than 60 inches. The door to the stall designated to be accessible in the restroom does not close automatically or have accessible hardware.	Modify or replace the stall designated to be accessible in the restroom so that it complies with ADAAG 4.17.3, CBC 1115B and CBC Figures 11B-1A and 1B. Standard accessible stalls require 60 inches in width with 56 inches depth for wall-mounted toilets or 59 inches depth for floor-mounted toilets to accommodate individuals in wheelchairs. The minimum width of a front-approach doorway shall provide at least 32 inches and a side-approach doorway shall provide at least 34 inches. The door shall swing outward, close automatically and provide accessible hardware.	\$4,000.00				
Record Number: 1372 There is no back grab bar in the stall designated to be accessible in the restroom.	Install a 36-inch back grab bar at a height of 33 inches above the finished floor in the stall designated to be accessible of the restroom. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material.	\$531.00				
Record Number: 1373 The side grab bar in the stall designated to be accessible in the restroom does not extend 54 inches from the back wall.	The front end of the grab bar shall extend at least 54 inches from the back wall and the back end of the grab bar shall be mounted within 12 inches from the back wall. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material.	\$531.00				
Record Number: 1374 The height of the toilet seat in the stall designated to be accessible in the restroom is less than 17 inches above the finished floor.	Remove or modify the toilet in the stall designated to be accessible in the restroom so that the seat height is between 17 inches and 19 inches above the finished floor (see ADAAG 4.16.3).	\$1,707.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1375 The distance from the center of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is less than 18 inches.	Relocate the toilet or stall side wall so that the distance from the centerline of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is exactly 18 inches (see ADAAG Figure 28).	\$1,143.00				
Record Number: 1376 The seat cover dispenser in the stall designated to be accessible in the restroom is mounted at a height greater than 40 inches and there is no clear floor space.	Relocate the seat cover dispenser in the stall designated to be accessible in the restroom so that the height is no greater than 40 inches above the finished floor (see CBC 1115B.9.2). Make certain that the location of the seat cover dispenser does not interfere with the use of a grab bar and provides sufficient clear floor space.	\$277.00				
Record Number: 1377 The knee clearance space under the lavatory designated to be accessible in the restroom is less than 29 inches. The knee depth space under the lavatory designated to be accessible in the restroom is less than 27 inches at 8 inches under the lavatory apron.	Remount or replace the lavatory designated to be accessible in the restroom to provide at least 29 inches of clear knee space between the finished floor and bottom of the lavatory apron. Make sure to provide at least 27 inches at 8 inches under the apron (see ADAAG 4.19.2).	\$1,286.00				
Record Number: 1378 The pipes under the lavatory in the restroom do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory designated to be accessible in the restroom to protect against contact (see ADAAG 4.19.4). Make certain there are no sharp or abrasive surfaces under the lavatory.	\$39.00				
Record Number: 1379 The bottom edge of the reflecting surface of the mirror in the restroom is greater than 40 inches above the finished floor.	Lower the mirror in the restroom so that the bottom edge of the reflecting surface is no higher than 40 inches above the finished floor and the topmost portion of the reflecting surface extends at least 74 inches above the finished floor (see ADAAG A4.19.6). A single, full-length mirror is recommended since it can accommodate all people. Make certain to provide a minimum clear floor space in front of the mirror of 30 inches in width and 48 inches in length.	\$291.00				
Record Number: 1380 The height of the controls and operating mechanisms for the soap dispenser in the restroom is greater than 40 inches in height.	Relocate the soap dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2).	\$277.00				
Disability Access Consultants, Inc. (800) 743-7067				Gym		

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1381 The height of the controls and operating mechanisms for the paper towel dispenser in the restroom is greater than 40 inches in height.	Relocate the paper towel dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2).	\$277.00				
Gym Women's Restroom						
Record Number: 1345 There is no signage indicating accessibility on the latch side of the entry door of the restroom. There is no Title 24 gender use signage on the entrance door.	The restroom is designated accessible and should be made accessible for the facility. Post signage centered 60 inches above the ground surface on the latch side of the entrance door identifying the restroom as accessible upon completion of the following items (see CBC 1115B., ADAAG 4.1.2(7) and ADAAG 4.1.6(3)(e). Signage shall include Braille and raised lettering, the gender or unisex use symbol and the ISA symbol. Post Title 24 gender use signage on the door @ 60" o.c. a.f.f.	\$58.00				
Record Number: 1346 There are six stalls located in the multiple accommodation restroom.	Create an accessible 36-inch wide alternate stall in addition to the required accessible standard stall in the multiple accommodation restroom. The accessible 36-inch wide alternate stall shall include an outward swinging, self-closing door and parallel side grab bars and shall provide at least 66 inches in length for a stall with a wall-mounted toilet or at least 69 inches in length for a stall with a floor-mounted toilet.	\$4,000.00				
Record Number: 1347 The height of the coat hook on the stall door is greater than 48 inches in height.	Relocate the coat hook on the stall door in the restroom to a maximum height of 48 inches above the floor surface (see CBC 1115B.9.2).	\$0.00				
Record Number: 1348 The door in the stall designated to be accessible in the restroom does not have appropriate accessible hardware.	Install a loop or U-shaped handle immediately below the latch hardware on the door to the stall designated to be accessible in the restroom (see CBC 1115B.7.1.3 and ADAAG 4.13.9). Lever-operated or push-type mechanisms may also be used. The latch shall be flip-over style, sliding or other hardware not requiring grasping or twisting.	\$189.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1349 The height of the back grab bar in the stall designated to be accessible of the restroom is greater than 33 inches above the finished floor.	Remount the back grab bar in the stall designated to be accessible in the restroom so that the height of the gripping surface is 33 inches above finished floor. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material.	\$448.00				
Record Number: 1350 The side grab bar in the stall designated to be accessible in the restroom does not extend 54 inches from the back wall.	The front end of the grab bar shall extend at least 54 inches from the back wall and the back end of the grab bar shall be mounted within 12 inches from the back wall. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material.	\$531.00				
Record Number: 1351 The flush control on the toilet in the stall designated to be accessible in the restroom is not on the wide (approach) side of the toilet.	Relocate the flush control on the toilet in the stall designated to be accessible in the restroom so that it is on the wide (approach) side of the toilet area (see ADAAG 4.16.5). Flush controls shall be hand-operated or automatic mechanisms.	\$127.00				
Record Number: 1352 The distance from the center of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is greater than 18 inches.	Relocate the toilet or stall side wall so that the distance from the centerline of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is exactly 18 inches (see ADAAG Figure 28).	\$1,143.00				
Record Number: 1353 The seat cover dispenser in the stall designated to be accessible in the restroom is mounted at a height greater than 40 inches and there is no clear floor space.	Relocate the seat cover dispenser in the stall designated to be accessible in the restroom so that the height is no greater than 40 inches above the finished floor (see CBC 1115B.9.2). Make certain that the location of the seat cover dispenser does not interfere with the use of a grab bar and provides sufficient clear floor space.	\$277.00				
Record Number: 1354 The knee clearance space under the lavatory designated to be accessible in the restroom is less than 29 inches. The knee depth space under the lavatory designated to be accessible in the restroom is less than 27 inches at 8 inches under the lavatory apron.	Replace the lavatory designated to be accessible in the restroom to provide at least 29 inches of clear knee space between the finished floor and bottom of the lavatory apron. Make sure to provide at least 27 inches at 8 inches under the apron (see ADAAG 4.19.2).	\$1,286.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1355 The pipes under the lavatory in the restroom do not provide protection against contact.	Insulate or otherwise configure pipes under the lavatory designated to be accessible in the restroom to protect against contact (see ADAAG 4.19.4). Make certain there are no sharp or abrasive surfaces under the lavatory.	\$39.00				
Record Number: 1356 The height of the controls and operating mechanisms for the soap dispenser in the restroom is greater than 40 inches in height.	Relocate the soap dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2).	\$277.00				
Record Number: 1357 The controls and operating mechanisms on the feminine products dispenser in the restroom require tight grasping, pinching, or twisting of the wrist and the use of two hands to operate. The height of the operating controls on the dispenser is at a height greater than 40 inches above the finished floor.	Modify or replace the feminine products dispenser in the restroom so that its controls and operating mechanisms can be operated with one hand and comply with ADAAG 4.27.4 and CBC 1117B.6.4. Make certain that the force to activate the operating controls shall be no greater than 5 pounds and that the height shall be no greater than 40 inches above the finished floor.	\$0.00				
Gym						
Drinking Fountains						
<i>Gym Drinking Fountain Outside of the Men's Restroom</i>						
Record Number: 1386 The spout outlet height is greater than 36 inches. The faucet controls require tight grasping or pinching of the wrist to operate.	Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirements and install a side rail or wing wall next to each side of the fountain. The height of the spout outlet shall not exceed 36 inches in height. Fountain controls shall be accessible.	\$2,216.00				
<i>Gym Men's Locker Room</i>						
Record Number: 1361 The faucet controls require tight grasping or pinching of the wrist to operate.	Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirements and install a side rail or wing wall next to each side of the fountain. Fountain controls shall be accessible.	\$2,216.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Gym Women's Locker Room Drinking Fountain						
Record Number: 1337						
The faucet controls require tight grasping or pinching of the wrist to operate.	Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirements and install a side rail or wing wall next to each side of the fountain. Fountain controls shall be accessible.	\$2,216.00				
Gym						
Assembly Areas						
Gym Bleachers						
Record Number: 1400						
There are pullout bleachers in the gymnasium. There are no wheelchair seating spaces located next to the bleachers.	Modify sections of the pullout bleachers in the Gymnasium to provide four accessible wheelchair seating locations with at least one fixed companion seat provided next to each accessible wheelchair seating area (see ADAAG 4.33.3 and ADAAG Figure 46). Where total seating capacity exceeds 300, accessible wheelchair seating spaces shall be provided in more than one location (see CBC 1104B.3.5 and ADAAG 4.33.3.)	\$237.00				
Gym Lobby						
Record Number: 1382						
The height of each ticket counter is greater than 34 inches.	Lower a portion of each ticket counter to a height no greater than 34 inches from the floor (see ADAAG 7.2).	\$1,044.00				
Record Number: 1383						
There is no signage indicating the availability of accessible seating in the Gymnasium at the ticket booth.	Provide a sign at the ticket booth indicating the availability of accessible seating locations at the Gymnasium (see CBC 1104B.3.4.1 and ADAAG 4.1.3(19)).	\$58.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Gym						
Locker Rooms						
<i>Gym Men's Accessible Shower</i>						
Record Number: 1366						
The water control lever provided in the shower compartment designated to be accessible in the men's locker room is at a height greater than 40 inches above the finished floor.	Remount the water control lever provided in the shower compartment designated to be accessible in the men's locker room at a height no greater than 40 inches above the finished floor. The centerline of the water control lever in the shower compartment designated to be accessible in the men's locker room shall be within 18 inches to 24 inches from the rear edge of the seat (see CBC 1115B.6.2.4.1).	\$554.00				
Record Number: 1367						
The hand-held sprayer unit is mounted at a height greater than 48 inches above the finished floor.	Install a hand-held sprayer unit in the shower compartment designated to be accessible in the men's locker room with a hose at least 60 inches in length. The centerline of the hand-held sprayer unit shall be mounted within 27 inches from the rear seat edge and at a height no greater than 48 inches from the finished floor (see CBC 1115B.6.2.4.2).	\$385.00				
<i>Gym Men's Locker Room</i>						
Record Number: 1360						
The urinal in the restroom does not provide a tapered, elongated rim. The height of the urinal rim is greater than 17 inches above the finished floor. The flush control valve on the urinal is greater than 44 inches above the finished floor.	Replace the urinal designated to be accessible in the restroom with a wall-mounted or stall-type tapered, elongated rim unit complying with ADAAG 4.18.2. The height of the rim surface of the urinal designated to be accessible shall not exceed 17 inches above the finished floor and the flush control valve shall not exceed a height of 44 inches above the finished floor.	\$951.00				
Record Number: 1362						
The width of the benches in the men's locker room is less than 24 inches. The benches in the men's locker room are not fixed to the wall along the longer dimension.	Install at least one bench with dimensions of 24 inches in width by 48 inches in length fixed to the wall along the longer dimension in the men's locker room. Mount the bench 17 inches to 19 inches above the finished floor with ADAAG 4.35.4 in the men's locker room. Provide sufficient clear floor space alongside the bench to allow a person using a wheelchair to make a parallel transfer onto the bench.	\$500.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
Record Number: 1363 The height of the equipment window is greater than 34 inches.	Lower at least a 36 inch wide portion of the equipment window to a maximum height between 28 and 34 inches (see CBC 1122B.4).	\$348.00				
Gym Women's Accessible Shower						
Record Number: 1343 There is no hand-held sprayer unit in the corner of the open shower area designated to be accessible in the women's locker room.	Install a hand-held sprayer unit in the corner of the open shower area designated to be accessible in the women's locker room with a hose at least 60 inches in length. The centerline of the hand-held sprayer unit shall be mounted within 27 inches from the rear seat edge and at a height no greater than 48 inches from the finished floor (see CBC 1115B.6.2.4.2).	\$385.00				
Record Number: 1344 There is only one grab bar provided. The 36-inch length grab bar is not mounted on the adjacent wall where the showerhead and controls are mounted.	Install a grab bar on each side of the required folding seat in the corner of the open shower area designated to be accessible in each locker room. The length of the grab bar along the same wall that the folding seat is affixed shall be 24 inches and a 36-inch length grab bar shall be mounted on the adjacent wall where the showerhead and controls are mounted (see CBC 1115B.6.2.4.2 and Figure 11B-2B).	\$531.00				
Gym Women's Locker Room						
Record Number: 1338 The benches in the women's locker room are not fixed to the wall along the longer dimension. There is insufficient clear floor space alongside the bench.	Install at least one bench with dimensions of 24 inches in width by 48 inches in length fixed to the wall along the longer dimension in the women's locker room. Mount the bench 17 inches to 19 inches above the finished floor with ADAAG 4.35.4 in the women's locker room. Provide sufficient clear floor space alongside the bench to allow a person using a wheelchair to make a parallel transfer onto the bench.	\$500.00				

Findings	Recommendations	Estimated Unit Cost	Actual Cost	Projected Finish Date	Actual Finish Date	Notes and Comments
<i>Gym Women's Private Shower Stall i</i>						
Record Number: 1342						
The length of the L-shaped grab bar is less than 24 inches by 36 inches.	Install one L-shaped grab bar in the corner across from the required folding seat in the shower compartment designated to be accessible of the women's locker room (see CBC 1115B.6.2.4.5 and CBC Figure 11B-2A and ADAAG 4.26). The grab bar shall be mounted on walls opposite and adjacent to the front edge of the seat, but not extended to include that portion of wall over the seat (see CBC 1115B.6.2.4.5)	\$531.00				
Gym						
Playground and Outdoor Sports Areas						
<i>Gym Outdoor Fitness Equipment</i>						
Record Number: 1405						
There is fitness equipment east of the Gym.	Provide an alternative fitness program at an accessible location for individuals with disabilities who are unable to use the fitness stations.	\$0.00				
<i>Gym Swimming Pool</i>						
Record Number: 1410						
No wheelchair seating is provided next to the bleachers.	Provide accessible wheelchair seating areas adjacent to the bleachers with equivalent line of sight as provided to members of the general public, if technically feasible; otherwise provide accessible wheelchair seating areas adjacent to the bleachers where unobstructed sight lines can be provided (see CBC 1104B.4 and ADAAG 4.33.3). The wheelchair seating area should be outlined, and have the International Symbol of Accessibility to reserve it for wheelchair users.	\$237.00				
Record Number: 1411						
There is no signage indicating the availability of accessible seating at the swimming pool.	Provide a sign indicating the availability of accessible seating locations at the swimming pool (see CBC 1104B.3.4.1 and ADAAG 4.1.3(19)).	\$58.00				
Facility Totals:		\$90,890.00				