

Facility Report

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|--|--|---------------------|-------------|-----------------------|--------------------|--------------------|
| Social Science | | | | | | |
| Path of Travel | | | | | | |
| <i>Social Science Break Room (Lower Floor) Sink</i> | | | | | | |
| Record Number: 1872 | | | | | | |
| The sink in break room is in an enclosed cabinet, thereby preventing an accessible forward approach. | Sinks in rooms must provide clear floor space in front of the sink for an accessible forward approach and shall provide at least 27 inches clear knee space and a minimum of nine inches clear toe space (see ADAAG 4.19.2). If neither clear floor space and knee and toe clearance can be provided, remove the sink cabinet and replace with an accessible wall-mounted sink unit. | \$420.00 | | | | |
| Record Number: 1873 | | | | | | |
| The pipes under the sink in break room does not provide protection against contact. | Insulate or otherwise configure pipes under the sink designated to be accessible in the room to protect against contact (see ADAAG 4.19.4). Make certain there are no sharp or abrasive surfaces under the sink. | \$39.00 | | | | |
| Record Number: 1874 | | | | | | |
| The faucet controls on the sink in the break room require tight grasping, pinching, or twisting of the wrist and are not accessible. | Install faucet controls complying with ADAAG 4.19.5 on the sink designated to be accessible in the break room. Lever-operated, push-type, touch-type or electronically controlled mechanisms are acceptable elements (see ADAAG 4.19.5). If self-closing valves are used the faucet shall remain open for at least 10 seconds. | \$392.00 | | | | |
| <i>Social Science Building Main Entrance</i> | | | | | | |
| Record Number: 1881 | | | | | | |
| The mat carpet runner does not adhere to the underlying floor surface and creates a hazardous path of travel. | Securely fasten the mats carpet runners or replace with a mat carpet runner that grips to the underlying floor surface to provide a firm, stable, continuous and relatively smooth path of travel surface (see CBC 1124B.3 and ADAAG 4.5.3). Mats or carpet runners along the primary path of travel shall provide beveled edges on all sides to prevent roll over. | \$659.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|--|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Social Science Room SS 214 | | | | | | |
| Record Number: 1882 | | | | | | |
| There is a raised platform in Room SS 214, preventing access to individuals with mobility impairments. | Since programs, services and activities to staff and the public are provided in this location, those programs, services and activities are required to be made accessible. It is recommended that a ramp be installed or other means of vertical access. | \$9,515.00 | | | | |
| Social Science Sidewalk | | | | | | |
| Record Number: 1889 | | | | | | |
| There are slopes greater than 5% on the primary path of travel to the Social Science Building. There are cross slopes greater than 2% on the primary path of travel. | Resurface the path of travel to provide a level surface that does not exceed a slope greater than 5%. Cross slopes shall not exceed 2%. | \$1,440.00 | | | | |
| Social Science Ramps | | | | | | |
| Social Science Exterior Ramp to the Business Building | | | | | | |
| Record Number: 1950 | | | | | | |
| The slope of the concrete ramp is greater than 8.33%. | Modify the run of the concrete ramp to provide a slope no greater than 8.33% with a cross slope not exceeding 2% (see CBC 1133B.5.3 and ADAAG 4.8.2). | \$4,920.00 | | | | |
| Record Number: 1951 | | | | | | |
| The length of the ramp exceeds the maximum distance allowed for its slope (rise). | Provide an intermediate landing on the ramp complying with CBC 1133B.5.4.1 and ADAAG 4.8.4 with a rise for each run of the ramp not exceeding 30 inches in height (see also ADAAG 4.8.2). | \$4,920.00 | | | | |
| Record Number: 1952 | | | | | | |
| There is only one handrail provided on the ramp. | Install a handrail on each side of the ramp that provide a continuous and smooth gripping surface diameter between 1 1/4 inches to 1 7/8 inches, mounted at a height between 34 inches and 38 inches and shall be at a distance no less than 1 1/2 inches from the adjacent wall. The ends of the handrail shall extend 12 inches in a parallel height from the top and bottom of the ramp and return smoothly to the post or wall. | \$1,200.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Social Science Interior Ramp Room SS 214 | | | | | | |
| Record Number: 1883 | | | | | | |
| The slope of the ramp is greater than 8.33%. | Modify the run of the ramp to provide a slope no greater than 8.33% with a cross slope not exceeding 2% (see CBC 1133B.5.3 and ADAAG 4.8.2). | \$4,920.00 | | | | |
| Record Number: 1884 | | | | | | |
| The ramp has no handrails. | Install handrails on each side of the ramp that provide a continuous and smooth gripping surface diameter between 1 1/4 inches to 1 7/8 inches, mounted at a height between 34 inches and 38 inches and shall be at a distance no less than 1 1/2 inches from the adjacent wall. The ends of the handrails shall extend 12 inches in a parallel height from the top and bottom of the ramp and return smoothly to the post or wall. | \$1,200.00 | | | | |
| Social Science | | | | | | |
| Elevators | | | | | | |
| Social Science Access to the Second Floor | | | | | | |
| Record Number: 1865 | | | | | | |
| There are programs, services and activities to staff, students and the public provided at this location. The interior stairway is the primary access with no other means to the area. | Since all programs, services and activities are required to be accessible, it is recommended that the program be relocated to an accessible area on an accessible level. Otherwise, another means of access to the location will be required. | \$0.00 | | | | |
| Social Science | | | | | | |
| Stairs | | | | | | |
| Social Science Exterior Stairs to Room SS 214 | | | | | | |
| Record Number: 1870 | | | | | | |
| There is no detectable striping on each tread of the exterior stairway. | Affix detectable contrasting striping to each tread of the stairway that clearly contrasts in color from the tread and is at least 2 inches in width placed no more than 1 inch from the tread nose or landing. | \$144.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|--|------------------------|----------------|--------------------------|-----------------------|-----------------------|
| <p>Record Number: 1871</p> <p>The handrails do not provide 12-inch extensions beyond the top and bottom treads of the stairway.</p> | <p>Install handrails on each side of stairway that provide a gripping surface between 1 1/4 to 1 1/2 inches with 12-inch top and bottom handrail extensions that extend beyond the top and bottom treads of the stairway which are parallel to the ground surface and return smoothly to the post or wall. Handrails shall be mounted at a height between 34 and 38 inches at a distance no less than 1 1/2 inches from the adjacent wall.</p> | \$528.00 | | | | |
| Social Science Exterior Stairs to Room SS 215 | | | | | | |
| <p>Record Number: 1867</p> <p>There is no detectable striping on each tread of the exterior stairway.</p> | <p>Affix detectable contrasting striping to each tread of the stairway that clearly contrasts in color from the tread and is at least 2 inches in width placed no more than 1 inch from the tread nose or landing.</p> | \$144.00 | | | | |
| <p>Record Number: 1868</p> <p>The handrails do not provide 12-inch extensions beyond the top and bottom treads of the stairway.</p> | <p>Install handrails on each side of stairway that provide a gripping surface between 1 1/4 to 1 1/2 inches with 12-inch top and bottom handrail extensions that extend beyond the top and bottom treads of the stairway which are parallel to the ground surface and return smoothly to the post or wall. Handrails shall be mounted at a height between 34 and 38 inches at a distance no less than 1 1/2 inches from the adjacent wall.</p> | \$528.00 | | | | |
| Social Science Exterior Stairs to the Business Building | | | | | | |
| <p>Record Number: 1887</p> <p>There is no detectable striping on each tread of the exterior stairway.</p> | <p>Affix detectable contrasting striping to each tread of the stairway that clearly contrasts in color from the tread and is at least 2 inches in width placed no more than 1 inch from the tread nose or landing.</p> | \$144.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|--|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1888 The handrails do not provide 12-inch extensions beyond the top and bottom treads of the stairway. The diameter of the gripping surface is greater than 1 7/8 inches. The ends of the handrails end abruptly. | Install handrails on each side of stairway that provide a gripping surface between 1 1/4 to 1 7/8 inches with 12-inch top and bottom handrail extensions that extend beyond the top and bottom treads of the stairway which are parallel to the ground surface and return smoothly to the post or wall. Handrails shall be mounted at a height between 34 and 38 inches at a distance no less than 1 1/2 inches from the adjacent wall. | \$528.00 | | | | |
| Social Science South Exterior Stairs | | | | | | |
| Record Number: 1885 There is no detectable striping on each tread of the exterior stairway. | Affix detectable contrasting striping to each tread of the stairway that clearly contrasts in color from the tread and is at least 2 inches in width placed no more than 1 inch from the tread nose or landing. | \$144.00 | | | | |
| Record Number: 1886 The handrails do not provide 12-inch extensions beyond the top and bottom treads of the stairway. | Install handrails on each side of stairway that provide a gripping surface between 1 1/4 to 1 1/2 inches with 12-inch top and bottom handrail extensions that extend beyond the top and bottom treads of the stairway which are parallel to the ground surface and return smoothly to the post or wall. Handrails shall be mounted at a height between 34 and 38 inches at a distance no less than 1 1/2 inches from the adjacent wall. | \$528.00 | | | | |
| Social Science | | | | | | |
| Doors | | | | | | |
| Social Science Exterior Door at Room SS 214 | | | | | | |
| Record Number: 1876 Exterior passage doors have push-bar/thumblatch hardware. | Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9). | \$834.00 | | | | |
| Social Science Exterior Door to Room SS 214 | | | | | | |
| Record Number: 1953 The bottom 10 inches of the door does not provide a smooth, uninterrupted surface, or panel to allow the door to be opened by a wheelchair footrest without creating a trap or hazardous condition, due to the door stop. | Remove the door stop to provide a smooth, uninterrupted surface for the bottom 10 inches of the door. | \$0.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Social Science Exterior Door to Room SS 215 | | | | | | |
| Record Number: 1869 | | | | | | |
| The exterior passage door has a round doorknob, which requires twisting of the wrist to operate. | Replace the existing door hardware with accessible hardware (see ADAAG 4.13.9). | \$834.00 | | | | |
| Social Science Interior Doors | | | | | | |
| Record Number: 1836 | | | | | | |
| Interior passage doors have round doorknobs, which require twisting of the wrist to operate. | Interior door hardware (doorknobs) should be changed to accessible lever-handled lockset hardware (see ADAAG 4.13.9). | \$204.00 | | | | |
| Social Science Restrooms | | | | | | |
| Social Science Faculty Unisex Restroom | | | | | | |
| Record Number: 1848 | | | | | | |
| There is no signage indicating accessibility on the latch side of the entry door of the restroom. There is no Title 24 gender use signage on the entrance door. | The restroom is designated accessible and should be made accessible for the facility. Post signage centered 60 inches above the ground surface on the latch side of the entrance door identifying the restroom as accessible upon completion of the following items (see CBC 1115B., ADAAG 4.1.2(7) and ADAAG 4.1.6(3)(e). Signage shall include Braille and raised lettering, the gender or unisex use symbol and the ISA symbol. Post Title 24 gender use signage on the door @ 60" o.c. a.f.f. | \$58.00 | | | | |
| Record Number: 1849 | | | | | | |
| The clear opening width of the entrance doorway to the restroom is less than 32 inches. | Widen the entrance doorway to the restroom to provide a clear opening width of at least 32 inches when the door is open 90 degrees (see ADAAG 4.13.5). | \$750.00 | | | | |
| Record Number: 1850 | | | | | | |
| The entrance door to the restroom has a round doorknob that requires tight grasping or twisting of the wrist to operate. | Replace the door hardware mounted on the restroom complying with ADAAG 4.13.9. Make certain accessible door hardware is mounted no higher than 48 inches above the finished floor. | \$204.00 | | | | |
| Record Number: 1851 | | | | | | |
| This restroom is not accessible and cannot be easily altered. There is not sufficient clear floor space in the restroom to accommodate an individual in a wheelchair. | Consult a design professional to modify the restroom. One or more walls may need to be moved to provide sufficient clear floor space to inscribe a 60-inch diameter turning radius in the restroom to accommodate an individual in a wheelchair. | \$0.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1852 There is no back grab bar in the restroom. | Install a 36-inch back grab bar at a height of 33 inches above the finished floor in the restroom. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material. | \$531.00 | | | | |
| Record Number: 1853 The height of the side grab bar in the restroom is greater than 33 inches above the finished floor. | Remount the side grab bar in the restroom so that the height of the gripping surface is 33 inches above the finished floor. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material. | \$448.00 | | | | |
| Record Number: 1854 The length of the side grab bar in the restroom is less than 42 inches. | Replace the side grab bar in the restroom with a 42 or 48-inch side grab bar complying with ADAAG 4.26 and CBC 1115B.8. The front end of the grab bar shall extend at least 54 inches from the back wall and the back end of the grab bar shall be mounted within 12 inches from the back wall. Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material. | \$531.00 | | | | |
| Record Number: 1855 The distance from the end of the side grab bar to the back wall in the restroom is greater than 12 inches. | Remount the side grab bar in the restroom so that it is not more than 12 inches from the back wall (see ADAAG Figure 29 and CBC 1115B.8). Grab bars must be able to support a point load of at least 250 pounds and shall be less than the allowable shear stress of the grab bar material. | \$448.00 | | | | |
| Record Number: 1856 The location of the toilet paper dispenser in the restroom is not within 12 inches of the front edge of the toilet seat. | Remount the toilet paper dispenser in the restroom so that it is within 12 inches from the front edge of the toilet seat (see CBC 1115B.9.3 and ADAAG Figure 29(b)). Toilet paper dispensers must allow continuous paper flow and shall not interfere with the use of the side grab bar. | \$277.00 | | | | |
| Record Number: 1857 The height of the toilet seat in the restroom is less than 17 inches above the finished floor. | Remove or modify the toilet in the restroom so that the seat height is between 17 inches and 19 inches above the finished floor (see ADAAG 4.16.3). | \$1,707.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1858 The seat cover dispenser in the restroom is mounted at a height greater than 40 inches and there is no clear floor space. | Relocate the seat cover dispenser in the restroom so that the height is no greater than 40 inches above the finished floor (see CBC 1115B.9.2). Make certain that the location of the seat cover dispenser does not interfere with the use of a grab bar and provides sufficient clear floor space. | \$277.00 | | | | |
| Record Number: 1859 The knee clearance space under the lavatory designated to be accessible in the restroom is less than 29 inches. The knee depth space under the lavatory designated to be accessible in the restroom is less than 27 inches at 8 inches under the lavatory apron. | Replace the lavatory designated to be accessible in the restroom to provide at least 29 inches of clear knee space between the finished floor and bottom of the lavatory apron. Make sure to provide at least 27 inches at 8 inches under the apron (see ADAAG 4.19.2). | \$1,286.00 | | | | |
| Record Number: 1860 The pipes under the lavatory in the restroom do not provide protection against contact. | Insulate or otherwise configure pipes under the lavatory designated to be accessible in the restroom to protect against contact (see ADAAG 4.19.4). Make certain there are no sharp or abrasive surfaces under the lavatory. | \$39.00 | | | | |
| Record Number: 1861 The bottom edge of the reflecting surface of the mirror in the restroom is greater than 40 inches above the finished floor. | Lower the mirror in the restroom so that the bottom edge of the reflecting surface is no higher than 40 inches above the finished floor and the topmost portion of the reflecting surface extends at least 74 inches above the finished floor (see ADAAG A4.19.6). A single, full-length mirror is recommended since it can accommodate all people. Make certain to provide a minimum clear floor space in front of the mirror of 30 inches in width and 48 inches in length. | \$291.00 | | | | |
| Record Number: 1862 The height of the controls and operating mechanisms for the soap dispenser in the restroom is greater than 40 inches in height. | Relocate the soap dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2). | \$277.00 | | | | |
| Record Number: 1863 The height of the controls and operating mechanisms for the paper towel dispenser in the restroom is greater than 40 inches in height. | Relocate the paper towel dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2). | \$277.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|--|--|---------------------|-------------|-----------------------|--------------------|--------------------|
| <p>Record Number: 1864</p> <p>The controls and operating mechanisms on the feminine products dispenser in the restroom require tight grasping, pinching, or twisting of the wrist and the use of two hands to operate. The height of the operating controls on the dispenser is at a height greater than 40 inches above the finished floor.</p> <p>Social Science Men's Restroom</p> | <p>Modify or replace the feminine products dispenser in the restroom so that its controls and operating mechanisms can be operated with one hand and comply with ADAAG 4.27.4 and CBC 1117B.6.4. Make certain that the force to activate the operating controls shall be no greater than 5 pounds and that the height shall be no greater than 40 inches above the finished floor.</p> | \$0.00 | | | | |
| <p>Record Number: 1837</p> <p>There is no signage indicating accessibility on the latch side of the entry door of the restroom.</p> | <p>The restroom is designated accessible and should be made accessible for the facility. Post signage centered 60 inches above the ground surface on the latch side of the entrance door identifying the restroom as accessible upon completion of the following items (see CBC 1115B., ADAAG 4.1.2(7) and ADAAG 4.1.6(3)(e). Signage shall include Braille and raised lettering, the gender or unisex use symbol and the ISA symbol. Post Title 24 gender use signage on the door @ 60" o.c. a.f.f.</p> | \$58.00 | | | | |
| <p>Record Number: 1838</p> <p>There is less than 18 inches on the latch side of the entrance door to the restroom from the pull side. There is less than 12 inches on the latch side of the entrance door to the restroom from the push side.</p> | <p>Consult a design professional to determine if it is technically feasible to provide at least 18 inches of latch side clearance at the entrance door to the restroom from the pull side and at least 12 inches from the push side (see ADAAG 4.13.6 and Figure 25). Otherwise, an automatic door opening device may be required to provide an accessible entrance.</p> | \$0.00 | | | | |
| <p>Record Number: 1839</p> <p>The urinal in the restroom does not provide a tapered, elongated rim. The height of the urinal rim is greater than 17 inches above the finished floor. The flush control valve on the urinal is greater than 44 inches above the finished floor.</p> | <p>Replace the urinal designated to be accessible in the restroom with a wall-mounted or stall-type tapered, elongated rim unit complying with ADAAG 4.18.2. The height of the rim surface of the urinal designated to be accessible shall not exceed 17 inches above the finished floor and the flush control valve shall not exceed a height of 44 inches above the finished floor.</p> | \$951.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|--|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1840 The door in the stall designated to be accessible in the restroom does not have appropriate accessible hardware. | Install a loop or U-shaped handle immediately below the latch hardware on the door to the stall designated to be accessible in the restroom (see CBC 1115B.7.1.3 and ADAAG 4.13.9). Lever-operated or push-type mechanisms may also be used. The latch shall be flip-over style, sliding or other hardware not requiring grasping or twisting. | \$189.00 | | | | |
| Record Number: 1841 The height of the toilet seat in the stall designated to be accessible in the restroom is less than 17 inches above the finished floor. | Remove or modify the toilet in the stall designated to be accessible in the restroom so that the seat height is between 17 inches and 19 inches above the finished floor (see ADAAG 4.16.3). | \$1,707.00 | | | | |
| Record Number: 1842 The distance from the center of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is greater than 18 inches. | Relocate the toilet or stall side wall so that the distance from the centerline of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is exactly 18 inches (see ADAAG Figure 28). | \$1,143.00 | | | | |
| Record Number: 1843 The seat cover dispenser in the stall designated to be accessible in the restroom is mounted at a height greater than 40 inches and there is no clear floor space. | Relocate the seat cover dispenser in the stall designated to be accessible in the restroom so that the height is no greater than 40 inches above the finished floor (see CBC 1115B.9.2). Make certain that the location of the seat cover dispenser does not interfere with the use of a grab bar and provides sufficient clear floor space. | \$277.00 | | | | |
| Record Number: 1844 The knee clearance space under the lavatory designated to be accessible in the restroom is less than 29 inches. The knee depth space under the lavatory designated to be accessible in the restroom is less than 27 inches at 8 inches under the lavatory apron. | Replace the lavatory designated to be accessible in the restroom to provide at least 29 inches of clear knee space between the finished floor and bottom of the lavatory apron. Make sure to provide at least 27 inches at 8 inches under the apron (see ADAAG 4.19.2). | \$1,286.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|--|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1845 The bottom edge of the reflecting surface of the mirror in the restroom is greater than 40 inches above the finished floor. | Lower the mirror in the restroom so that the bottom edge of the reflecting surface is no higher than 40 inches above the finished floor and the topmost portion of the reflecting surface extends at least 74 inches above the finished floor (see ADAAG A4.19.6). A single, full-length mirror is recommended since it can accommodate all people. Make certain to provide a minimum clear floor space in front of the mirror of 30 inches in width and 48 inches in length. | \$291.00 | | | | |
| Record Number: 1846 The height of the controls and operating mechanisms for the soap dispenser in the restroom is greater than 40 inches in height. Social Science Women's Restroom | Relocate the soap dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2). | \$277.00 | | | | |
| Record Number: 1826 There is no signage indicating accessibility on the latch side of the entry door of the restroom. There is no Title 24 gender use signage on the entrance door. | The restroom is designated accessible and should be made accessible for the facility. Post signage centered 60 inches above the ground surface on the latch side of the entrance door identifying the restroom as accessible upon completion of the following items (see CBC 1115B., ADAAG 4.1.2(7) and ADAAG 4.1.6(3)(e). Signage shall include Braille and raised lettering, the gender or unisex use symbol and the ISA symbol. Post Title 24 gender use signage on the door @ 60" o.c. a.f.f. | \$58.00 | | | | |
| Record Number: 1827 There is less than 18 inches on the latch side of the entrance door to the restroom from the pull side. There is less than 12 inches on the latch side of the entrance door to the restroom from the push side. | Consult a design professional to determine if it is technically feasible to provide at least 18 inches of latch side clearance at the entrance door to the restroom from the pull side and at least 12 inches from the push side (see ADAAG 4.13.6 and Figure 25). Otherwise, an automatic door opening device may be required to provide an accessible entrance. | \$0.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|--|----------------------------|--------------------|------------------------------|---------------------------|---------------------------|
| Record Number: 1828 The door in the stall designated to be accessible in the restroom does not have appropriate accessible hardware. | Install a loop or U-shaped handle immediately below the latch hardware on the door to the stall designated to be accessible in the restroom (see CBC 1115B.7.1.3 and ADAAG 4.13.9). Lever-operated or push-type mechanisms may also be used. The latch shall be flip-over style, sliding or other hardware not requiring grasping or twisting. | \$189.00 | | | | |
| Record Number: 1829 The flush control on the toilet in the stall designated to be accessible in the restroom is not on the wide (approach) side of the toilet. | Relocate the flush control on the toilet in the stall designated to be accessible in the restroom so that it is on the wide (approach) side of the toilet area (see ADAAG 4.16.5). Flush controls shall be hand-operated or automatic mechanisms. | \$127.00 | | | | |
| Record Number: 1830 The height of the toilet seat in the stall designated to be accessible in the restroom is less than 17 inches above the finished floor. | Remove or modify the toilet in the stall designated to be accessible in the restroom so that the seat height is between 17 inches and 19 inches above the finished floor (see ADAAG 4.16.3). | \$1,707.00 | | | | |
| Record Number: 1831 The distance from the center of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is greater than 18 inches. | Relocate the toilet or stall side wall so that the distance from the centerline of the toilet to the nearest side wall in the stall designated to be accessible in the restroom is exactly 18 inches (see ADAAG Figure 28). | \$1,143.00 | | | | |
| Record Number: 1832 The seat cover dispenser in the stall designated to be accessible in the restroom is mounted at a height greater than 40 inches and there is no clear floor space. | Relocate the seat cover dispenser in the stall designated to be accessible in the restroom so that the height is no greater than 40 inches above the finished floor (see CBC 1115B.9.2). Make certain that the location of the seat cover dispenser does not interfere with the use of a grab bar and provides sufficient clear floor space. | \$277.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1833 The bottom edge of the reflecting surface of the mirror in the restroom is greater than 40 inches above the finished floor. | Lower the mirror in the restroom so that the bottom edge of the reflecting surface is no higher than 40 inches above the finished floor and the topmost portion of the reflecting surface extends at least 74 inches above the finished floor (see ADAAG A4.19.6). A single, full-length mirror is recommended since it can accommodate all people. Make certain to provide a minimum clear floor space in front of the mirror of 30 inches in width and 48 inches in length. | \$291.00 | | | | |
| Record Number: 1834 The height of the controls and operating mechanisms for the soap dispenser in the restroom is greater than 40 inches in height. | Relocate the soap dispenser in the restroom to a maximum height of 40 inches for all the controls and operating mechanisms (see CBC 1115B.9.2). | \$277.00 | | | | |
| Record Number: 1835 The controls and operating mechanisms on the feminine products dispenser in the restroom require tight grasping, pinching, or twisting of the wrist and the use of two hands to operate. The height of the operating controls on the dispenser is at a height greater than 40 inches above the finished floor. | Modify or replace the feminine products dispenser in the restroom so that its controls and operating mechanisms can be operated with one hand and comply with ADAAG 4.27.4 and CBC 1117B.6.4. Make certain that the force to activate the operating controls shall be no greater than 5 pounds and that the height shall be no greater than 40 inches above the finished floor. | \$0.00 | | | | |
| Social Science | | | | | | |
| Drinking Fountains | | | | | | |
| <i>Social Science Drinking Fountain</i> | | | | | | |
| Record Number: 1847 The drinking fountain is not a "high-low" type. | Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirements and install a side rail or wing wall next to each side of the fountain. Wall-mounted drinking fountains shall provide a minimum knee clearance height of 27 inches, 30 inches in width and between 18 inches and 19 inches in fountain depth. | \$2,216.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|--|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Social Science Drinking Fountain on the Lower Floor | | | | | | |
| Record Number: 1875 | | | | | | |
| The drinking fountain at the Social Science Building is not a high-low type. | Fifty percent of the drinking fountains on primary paths of travel shall be accessible (see CBC 1117B.1 and ADAAG 4.15). Install a "high-low" fountain design to comply with both state and federal requirements and install a side rail or wing wall next to each side of the fountain. Provide at least 30 inches in width and 48 inches in depth in front of the drinking fountain. The height of the spout outlet shall not exceed 36 inches in height. Fountain controls shall be accessible. The spout shall direct the water flow at least 4 inches high and in a trajectory that is parallel or nearly parallel to the front of the drinking fountain. Wall-mounted drinking fountains shall provide a minimum knee clearance height of 27 inches, 30 inches in width and between 18 inches and 19 inches in fountain depth. | \$2,216.00 | | | | |
| Social Science | | | | | | |
| Assembly Areas | | | | | | |
| Social Science Room SS 210 | | | | | | |
| Record Number: 1878 | | | | | | |
| There is fixed seating in Social Science Room 210. There are no wheelchair seating spaces. | Provide accessible wheelchair seating spaces in the Social Science Room 210 that provide viewing positions with a line of sight comparable to those of the general public (see ADAAG 4.1.3(19) and ADAAG 4.33.2). At least one companion fixed seat complying with ADAAG 4.33.3 should be provided next to each wheelchair seating space. Readily removable seats may be installed in wheelchair spaces when the spaces are not required to accommodate wheelchair users (see CBC 1104B.3.7 and ADAAG 4.1.3(19). Where total seating capacity exceeds 300, accessible wheelchair seating spaces shall be provided in more than one location (see CBC 1104B.3.5 and ADAAG 4.33.3.) One percent, but not less than one of all fixed seats shall be aisle seats with no armrests on the aisle side, or removable or folding armrests. Each such seat shall be marked accessible (ADAAG 4.33.4) | \$237.00 | | | | |

| Findings | Recommendations | Estimated Unit Cost | Actual Cost | Projected Finish Date | Actual Finish Date | Notes and Comments |
|---|---|---------------------|-------------|-----------------------|--------------------|--------------------|
| Record Number: 1880 There is no signage indicating the availability of accessible seating in Room SS 210. Social Science Room SS 214 | Provide signage indicating the availability of accessible seating locations in Room SS 210 (see CBC 1104B.3.4.1 and ADAAG 4.1.3(19)). | \$58.00 | | | | |
| Record Number: 1877 There is fixed seating in the Social Science Room 214. There are no wheelchair seating spaces provided. | Provide accessible wheelchair seating spaces in Room SS 214 that provide viewing positions with a line of sight comparable to those of the general public (see ADAAG 4.1.3(19) and ADAAG 4.33.2). At least one companion fixed seat complying with ADAAG 4.33.3 should be provided next to each wheelchair seating space. Readily removable seats may be installed in wheelchair spaces when the spaces are not required to accommodate wheelchair users (see CBC 1104B.3.7 and ADAAG 4.1.3(19). Where total seating capacity exceeds 300, accessible wheelchair seating spaces shall be provided in more than one location (see CBC 1104B.3.5 and ADAAG 4.33.3.) One percent, but not less than one of all fixed seats shall be aisle seats with no armrests on the aisle side, or removable or folding armrests. Each such seat shall be marked accessible (ADAAG 4.33.4) | \$237.00 | | | | |
| Record Number: 1879 There is no signage indicating the availability of accessible seating in Room SS 214. Social Science Room SS 215 | Provide signage indicating the availability of accessible seating locations in Room SS 214 (see CBC 1104B.3.4.1 and ADAAG 4.1.3(19)). | \$58.00 | | | | |
| Record Number: 1866 The projection room in the Social Science Building is accessible only by stairs. | Provide an alternate relay location with accessible electronic control devices so individuals with mobility impairments may participate in programs, services and activities provided at the projection booth. | \$0.00 | | | | |
| | Facility Totals: | \$56,856.00 | | | | |