

Backflow Prevention Devices at Gavilan Community College

No	Manufacturer	Model Number	Serial Number	Valve size	Valve Type	Location	Initial Date Tested	Final Date Tested
1	Wilkins	975 XL	2741215	2"	RP	Business Office Building	2/17/2018	
2	Wilkins	975XL	3056816	1 1/2"	RP	Business Office Building	2/17/2018	
3	Febco	825YA	J009227	2"	RP	Child Development Center under enclosure	2/17/2018	
4	Wilkins	975XL2	3702536	2"	RP	Health Occupations Building under enclosure	2/17/2018	
5	Wilkins	975XL	2388452	2"	RP	Math bldg. Boiler Room nw corner	2/28/2018	
6	Wilkins	975XL	2356646	1 1/2"	RP	Math Bldg. Boiler Room se corner	2/28/2018	
7	Wilkins	975XL	2388453	2"	RP	Business Unit Boiler Room North Wall	2/28/2018	
8	Wilkins	975XL	2356641	1 1/2"	RP	Business Unit Boiler Room South Wall	2/28/2018	
9	Wilkins	975XL	2739081	2"	RP	Administration Building sw corner under enclosure	2/17/2018	
10	Febco	825YD	9707151242	2 1/2"	RP	Student Center nw corner yard	2/17/2018	
11	Febco	825Y	H14574	2"	RP	Gymnasium nw corner under enclosure	3/15/2017	
12	Wilkins	375	L29752	2 1/2"	RP	Adaptive PE Boiler Room	2/28/2018	
13	Wilkins	975XL	2299812	1"	RP	Adaptive PE Boiler Room	2/28/2018	
14	Wilkins	975XL2	4020712	2"	RP	Portable #6 under enclosure	2/18/2017	
*15	Watts Regulator	909	187219	3"	RP	Baseball Fields under enclosure	3/4/2018	
16	Wilkins	375	35486	3"	RP	Baseball Fields inside storage area	3/15/2017	
17	Wilkins	975XL	1290887	3/4"	RP	Theater Chiller Room	2/28/2018	
18	Wilkins	975XL	1569295	1"	RP	T V Studio - Chiller pad	2/28/2018	
19	Wilkins	975XL	1054809	1"	RP	CDC chiller	2/28/2018	
20	Wilkins	975XL	1571040	3/4"	RP	HOB Chiller	2/28/2018	
22	Febco	805Y	A149560	2"	DC	South side of Library next to transformer	2/17/2018	
23	Wilkins	975XL2	3384055	2"	RP	East side of Library	2/17/2018	
24	Watts Regulator	009QT	A62224	1/2"	RP	IT Server Room MP Building	2/28/2018	
25	Wilkins	975XL	115711	3/4"	RP	CDC Water Heater Room	2/28/2018	
26	Wilkins	975XL	1111738	3/4"	RP	HOB Water Heater Room	2/28/2018	
27	Febco	LF880V	N1109031107	6"	RP	Maintenance Security Building	2/28/2018	
28	Watts Regulator	LF009M2QT	87316	2"	RP	Pool Area	2/28/2018	
29	Wilkins	375	L101880	10"	RP	CV in front near street Fire supression	3/6/2018	
30	Wilkins	475	Q09956	4"	RP	CV in front near street irrigation	3/6/2018	
31	Febco	LF 860	16180908	3"	RP	CV In front of street irrigation	3/29/2018	
<p>*Notes: comments below refer to vales repaired or replaced, all other valves passed inspection without issue.</p>								
Device dumping - installed complete rebuild kit #15								
Line leaking temporarily out of use #11								
Portable 6 out of use # 14								
Backflow has been deleted # 16								